PPG Facility 2001 and 2000 TRI Dioxin Data

TEQ

PPG Corporation - TEQ		70669PPGNDCOLUM		26155PPGNDSTATE			
		Lake Charles	Lake Charles	New Martinsville	New Martinsville	TOTAL	TOTAL
		2001	2000	2001	2000	2001	2000
TRI On-Site Reported Releases of Dioxins							
5.1 & 5.2	TOTAL Air Emissions	0.03	0.03	0.03	0.03	0.06	0.06
5.3.1	Surface Water Discharges	4.76	8.96	0.30	0.30	5.06	9.26
5.5.2	Releases to Land Surface	0.00	0.00	0.00	0.00	0.00	0.00
	TOTAL Release to Open Environment	4.79	8.99	0.34	0.34	5.13	9.33
TRI On-Site Disposal of Dioxins							
5.5.1A	Hazardous Waste Landfills	0.00	0.00	0.00	0.00	0.00	0.00
5.5.1B	Other Landfills	0.00	0.00	0.00	0.00	0.00	0.00
5.4.1/5.4.2	Underground Injection	0.00	0.00	0.00	0.00	0.00	0.00
	On-Site Disposal	0.00	0.00	0.00	0.00	0.00	0.00
TRI Transfers Off-Site for Further Waste Mgmt							
	TOTAL Off-Site Transfers	2.29	8.69	0.07	0.03	2.37	8.72
M93	Transfers to Recycling	0.00	0.00	0.00	0.00	0.00	0.00
M56	Transfers to Energy Recovery	0.00	0.00	0.00	0.00	0.00	0.00
M50+	Transfers to Treatment	1.88	3.77	0.00	0.00	1.88	3.77
M72&M79	Transfers to Off-Site Land Disposal	0.42	4.92	0.07	0.03	0.49	4.95
M90	Other Off-Site Transfers	0.00	0.00	0.00	0.00	0.00	0.00
Quantities of Dioxin in Waste							
	TOTAL Quantity in Waste	239.20	276.67	0.00	0.00	239.20	276.67
8.4	Recycled On-Site	0.00	0.00	0.00	0.00	0.00	0.00
8.5	Recycled Off-Site	0.00	0.00	0.00	0.00	0.00	0.00
8.2	Energy Recovery On-Site	0.00	0.00	0.00	0.00	0.00	0.00
8.3	Energy Recovery Off-Site	0.00	0.00	0.00	0.00	0.00	0.00
8.6	Treated On-Site	237.32	272.90	0.00	0.00	237.32	272.90
8.7	Treated Off-Site	1.88	3.77	0.00	0.00	1.88	3.77
8.8	Recovered via Remediation	0.00	0.00	0.00	0.00	0.00	0.00

PPG Facility 2001 and 2000 TRI Dioxin Data

TM-17

PPG Corporation - TM-17		70669PPGNDCOLUM		26155PPGNDSTATE			
		Lake Charles	Lake Charles	New Martinville	New Martinville	TOTAL	TOTAL
		2001	2000	2001	2000	2001	2000
TRI On-Site Reported Releases of Dioxins							
5.1 & 5.2	TOTAL Air Emissions	1.33	1.33	0.71	0.73	2.03	2.06
5.3.1	Surface Water Discharges	42.08	74.81	2.81	2.81	44.88	77.62
5.5.2	Releases to Land Surface	0.00	0.00	0.00	0.00	0.00	0.00
	TOTAL Release to Open Environment	43.41	76.14	3.51	3.54	46.92	79.68
TRI On-Site Disposal of Dioxins							
5.5.1A	Hazardous Waste Landfills	0.00	0.00	0.00	0.00	0.00	0.00
5.5.1B	Other Landfills	0.00	0.00	0.00	0.00	0.00	0.00
5.4.1/5.4.2	Underground Injection	0.00	0.00	0.00	0.00	0.00	0.00
	On-Site Disposal	0.00	0.00	0.00	0.00	0.00	0.00
TRI Transfers Off-Site for Further Waste Mgmt							
	TOTAL Off-Site Transfers	239.34	430.55	0.81	0.32	240.15	430.87
M93	Transfers to Recycling	0.00	0.00	0.00	0.00	0.00	0.00
M56	Transfers to Energy Recovery	0.00	0.00	0.00	0.00	0.00	0.00
M50+	Transfers to Treatment	154.03	296.60	0.00	0.00	154.03	296.60
M72&M79	Transfers to Off-Site Land Disposal	85.30	133.95	0.81	0.32	86.12	134.27
M90	Other Off-Site Transfers	0.00	0.00	0.00	0.00	0.00	0.00
Quantities of Dioxin in Waste							
	TOTAL Quantity in Waste	14212.23	15858.60	0.00	0.00	14212.23	15858.60
8.4	Recycled On-Site	0.00	0.00	0.00	0.00	0.00	0.00
8.5	Recycled Off-Site	0.00	0.00	0.00	0.00	0.00	0.00
8.2	Energy Recovery On-Site	0.00	0.00	0.00	0.00	0.00	0.00
8.3	Energy Recovery Off-Site	0.00	0.00	0.00	0.00	0.00	0.00
8.6	Treated On-Site	14058.20	15562.00	0.00	0.00	14058.20	15562.00
8.7	Treated Off-Site	154.03	296.60	0.00	0.00	154.03	296.60
8.8	Recovered via Remediation	0.00	0.00	0.00	0.00	0.00	0.00